

CCP Instruction Sheet

Warning! This tool should not be used on live electrical circuits. It is not protected against electrical shock! Always use OSHA/ANSI or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool.

The Cablematic CCP cutting tool provides clean, square, and burr-free cuts to PVC/Poly Pipe, Coax (Braided Smooth-Corrugated), Conduit, Innerduct, Tubing and Hose. This tool is particularly useful for making clean end cuts on LMR[®] cable prior to cable strip preparation.

Features:

- Cutting capacity up to 1-1/4" OD
- Scissor type, spring action frame for ease of use
- Latch lock to safely close tool
- Replaceable blade



Operation:

1. Place cable or pipe in tool at desired cut location.
2. Firmly squeeze handles to apply blade pressure on cable/pipe while simultaneously rocking the tool back and forth 180 degrees, as depicted at right.
3. Continue until cable/pipe is cut off.



CCP tool: Part No. 42940

CCP Replacement Blade: Part No. 42941

WARRANTY: RIPLEY warrants its products against defective materials and workmanship for a period of one year from date of shipment from the RIPLEY factory provided the product is utilized in accordance with instructions and specified ratings.



46 Nooks Hill Road, Cromwell, CT 06416 USA ~ Phone: 800-528-8665 ~ Int'l: (01) 860-635-2200
Fax: (01) 860-635-3631 ~ E-mail: info@ripley-tools.com ~ Internet: www.ripley-tools.com



CCP instru
11-24-15ff